



1989

BOMBARDIER LEARJET 35A

SN 35A-648





1989

BOMBARDIER LEARJET 35A

SN 35A-648

7,960 FH

TOTAL TIME

5,874 FC

TOTAL CYCLES

HIGHLIGHTS

- Engines enrolled on Honeywell MSP Gold Maintenance Program
- Fresh Phase A, B & D Inspections | Gross Weight Increase Modification
- Interior Refurbished in May 2022 | ADS-B Out
- AirText Messaging Service Module (SMS, Whatsapp & iMessage)

Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties. Verification of specifications remain the sole responsibility of purchaser. Photographs and images may have been modified to remove logos, registration marks, or other identifying information to protect the privacy of the Aircraft's current owner. The Aircraft is subject to prior sale, lease, and/or removal from the market without prior notice.

1989 BOMBARDIER LEARJET 35A SN 35A-648 INTERIOR



Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties. Verification of specifications remain the sole responsibility of purchaser. Photographs and images may have been modified to remove logos, registration marks, or other identifying information to protect the privacy of the Aircraft's current owner. The Aircraft is subject to prior sale, lease, and/or removal from the market without prior notice.



@aleaerolineasoficial



+52 55 4209 0200



+52 55 4944 0307

INFO@ALE.MX

ALE.MX

1989 BOMBARDIER LEARJET 35A SN 35A-648 INTERIOR



Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties. Verification of specifications remain the sole responsibility of purchaser. Photographs and images may have been modified to remove logos, registration marks, or other identifying information to protect the privacy of the Aircraft's current owner. The Aircraft is subject to prior sale, lease, and/or removal from the market without prior notice.

1989 BOMBARDIER LEARJET 35A SN 35A-648 INTERIOR



Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties. Verification of specifications remain the sole responsibility of purchaser. Photographs and images may have been modified to remove logos, registration marks, or other identifying information to protect the privacy of the Aircraft's current owner. The Aircraft is subject to prior sale, lease, and/or removal from the market without prior notice.



@aleaerolineasoficial



+52 55 4209 0200



+52 55 4944 0307

INFO@ALE.MX

ALE.MX

1989 BOMBARDIER LEARJET 35A SN 35A-648 EXTERIOR



Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties. Verification of specifications remain the sole responsibility of purchaser. Photographs and images may have been modified to remove logos, registration marks, or other identifying information to protect the privacy of the Aircraft's current owner. The Aircraft is subject to prior sale, lease, and/or removal from the market without prior notice.



@aleaerolineasoficial



+52 55 4209 0200



+52 55 4944 0307

INFO@ALE.MX

ALE.MX

1989 BOMBARDIER LEARJET 35A SN 35A-648 COCKPIT



Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties. Verification of specifications remain the sole responsibility of purchaser. Photographs and images may have been modified to remove logos, registration marks, or other identifying information to protect the privacy of the Aircraft's current owner. The Aircraft is subject to prior sale, lease, and/or removal from the market without prior notice.

1989 BOMBARDIER LEARJET 35A SN 35A-648

AIRFRAME

Entry Into Service Date	23-Jul-89
Total Time Since New	7,960 FH
Total Cycles Since New	5,874 FC
Home Base	TLC / MMT0
Program Coverage	No
Maintenance Tracking	-
Registration	N97LE
Certification	FAA Part 91

CONNECTIVITY & ENTERTAINMENT

Monitors	No
Wi-Fi	No
Satcom	No
Others	AirText Messaging Service (SMS, Whatsapp & iMessage)

ENGINES

#1

#2

	#1	#2
Model	Honeywell TFE731-2-2B	
Serial Number	P-89676	P-89678
Total Hours Since New	7,749 FH	7,921 FH
Total Cycles Since New	5,987 FC	5,898 FC
Time Between Overhaul	4,200 FH	
Total Hours Since Overhaul	3,762 FH	3,933 FH
Total Cycles Since Overhaul	3,114 FC	3,039 FC
Program Coverage	Honeywell MSP Gold	

ADDITIONAL EQUIPMENT & FEATURES

ADS-B Out
N1 DEECs
Honeywell KMD-540 MFD
Dual IS&S Air Data Systems
Dee Howard 4000 Thrust Reversers
Gross Weight Increase Modification
Executive Door

Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties. Verification of specifications remain the sole responsibility of purchaser. Photographs and images may have been modified to remove logos, registration marks, or other identifying information to protect the privacy of the Aircraft's current owner. The Aircraft is subject to prior sale, lease, and/or removal from the market without prior notice.



@aleaerolineasoficial



+52 55 4209 0200



+52 55 4944 0307

INFO@ALE.MX

ALE.MX

AVIONICS

Collins Pro Line II Avionics Suite comprised of:

Unit Type	Quantity	Description
ADC (Air Data Computer)	Dual	Kollsman 621, Collins 590A-3J1
ADF (Automatic Direction Finder)	Single	Collins ADF-60A
AP (Autopilot)	Single	Electromech Technologies EM2096-5
COMMS (VHF Comms)	Dual	Collins VHF-22A
COMPASS	Single	Airpath Instrutment C2340L4-M23
CVR (Cockpit Voice Recorder)	Single	Collins ADF-60A
DME (Distance Measuring Equipment)	Dual	Collins DME-42
EFIS (Electronic Flight Instrument Sys.)	-	Collins FIS-84
ELT (Emergency Locator Beacon)	Single	King 110-406
FD (Flight Director)	Single	JET DN-104A
FGC (Flight Guidance Computer)	Single	Collins FGC-80B
FMS (Flight Management Sys.)	Dual	Universal UNS-1
GYROSCOPE	Dual	JET RG-227E; Collins VG-206D
HSI (Horizontal Situation Indicator)	Dual	Collins HPU-74
NAV (Navigation Radio)	Dual	Collins VIR-32
RAD ALT (Radar Altimeter)	Single	Collins ALT-55B
RMI (Radio Magnetic Indicator)	Dual	Aeronetics 3137L-B-2-1-C
ST ALT (Standby Altimeter)	Single	Aerosonic Corp.
TAWS (Terrain Awareness Sys.)	Single	Honeywell KGP-560 EGPWS
TCAS (Traffic Collision Avoidance Sys.)	Single	Honeywell TPU-66A TCAS-I
XPDR (Transponder)	Dual	Garmin GTX-335
WX RAD (Weather Radar)	Single	Honeywell WU-850

MAJOR INSPECTION STATUS

Inspection	Last Performed	Next Due
Phase A1-A6 (300 FH / 12 M)	12-May-23 (7,945 FH)	12-May-24 / 8,245 FH
Phase B1-B6 (600 FH / 24 M)	12-May-23 (7,945 FH)	12-May-25 / 8,545 FH
Phase C1-C6 (1,200 FH / 48 M)	23-Dec-20 (7,672 FH)	23-Dec-24 / 8,872 FH
Phase D1-D6 (2,400 FH / 96 M)	12-May-23 (7,945 FH)	12-May-31 / 10,345 FH
3,000 Landings	18-May-14 (7,383 FC)	8,759 FC
6,000 Landings	18-May-14 (7,383 FC)	11,759 FC
Eng 1 MPI (1,400 FH)	04-Mar-11 (6,830 FH)	8,230 FH
Eng 2 MPI (1,400 FH)	28-Feb-08 (6,684 FH)	8,084 FH
Eng 1 CZI (4,200 FH)	13-Aug-01 (3,987 FH)	8,187 FH
Eng 2 CZI (4,200 FH)	15-Aug-01 (3,988 FH)	8,188 FH
12 Year Airframe	18-May-14 (7,383 FH)	18-May-26
All maintenance reported to be up to date		

Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties. Verification of specifications remain the sole responsibility of purchaser. Photographs and images may have been modified to remove logos, registration marks, or other identifying information to protect the privacy of the Aircraft's current owner. The Aircraft is subject to prior sale, lease, and/or removal from the market without prior notice.

1989 BOMBARDIER LEARJET 35A SN 35A-648


INTERIOR

Number of Passengers	Eight (8) Passengers
Refreshment Center	Forward RS
Fwd. Cabin Config.	One (1) Side-Facing + Two (2) Fwd-Facing Seats
Aft Cabin Config.	Two (2) Aft-Facing Seats + Three (3) Place Divan
Lavatory Location	Forward (Belted)
Refurbish Date	May 2022

EXTERIOR

Base Color	White & Grey
Stripe Colors	Blue
Re-Paint Date	July 1997

FLOORPLAN



8 PAX

Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties. Verification of specifications remain the sole responsibility of purchaser. Photographs and images may have been modified to remove logos, registration marks, or other identifying information to protect the privacy of the Aircraft's current owner. The Aircraft is subject to prior sale, lease, and/or removal from the market without prior notice.

A LOCAL ALLY,
AN EXPERT WITHOUT BORDERLINES.



@aleaerolineasoficial



+52 55 4209 0200



+52 55 4944 0307

| INFO@ALE.MX

| ALE.MX

